PlugFest Packing List

Note: Long power strips are supplied by IoL.

Tools:
- Small flathead screwdriver
- Other screwdrivers as needed
- Wire cutter/strippers
- Electrical tape
- Other tools as needed

Ethernet:
- Ethernet cables
- Spare Ethernet cables
- At least (1) extra long Ethernet cable (10ft, 3m)
- Ethernet switch (with port mirroring)

MS/TP:
- MS/TP cable
- MS/TP connectors
- MS/TP packet sniffer

Miscellaneous:
- Return shipping labels and documentation
- Power supplies and transformers
- USB-C to Ethernet connector
- Hub / switch large enough to connect all of your products and laptops and to connect to the other team's hub/switch.
- Laptops and tools needed to configure and debug your product setup (such as WireShark, your configuration tools, and possibly your development environment).