



PlugFest Packing List

Long power strips are supplied by IoL.

Tools:

- Small flathead screwdriver
- Other screwdrivers as needed
- Wire cutter/strippers
- Electrical tape
- Other tools as needed

Ethernet:

- Ethernet cables
- Spare Ethernet cables
- At least (1) extra long Ethernet cable (10ft, 3m)
- Ethernet switch (with port mirroring)

MS/TP:

- MS/TP cable
- MS/TP connectors
- MS/TP packet sniffer

Miscellaneous:

- Return shipping labels and documentation
- Power supplies and transformers
- USB-C to Ethernet connector